

# Test Report

Report No. A225055325110100101

Page 1 of 4

Company Name PCBWay

Shown on Report

Address ROOM 1105-1108, NO. 2 BUILDING, EST MALL BUSINESS CENTER,  
NO. 698 CHANGBANG ROAD, XIACHENG DISTRICT, 310004,  
HANGZHOU, CHINA

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client

|                      |                            |
|----------------------|----------------------------|
| Sample Name          | sample1                    |
| Material             | pcb                        |
| Sample Received Date | Aug. 4, 2025               |
| Testing Period       | Aug. 4, 2025-Aug. 19, 2025 |

## Test Requested

| No. | Test Item         |
|-----|-------------------|
| 1   | Voltage resistant |

Test Result(s): Please see the following pages.

Approved by Annie LangDate Aug. 19, 2025Annie Lang  
Approved Signatory

No. RDBB46D599

Centre Testing International Group Co., Ltd. Hongwei Industrial Park, Zone 70, Bao'an District, Shenzhen, Guangdong, China

Test Report

Report No. A225055325110100101

Page 2 of 4

Tested Sample(s)

| Sample No.        | Sample Name | Material |
|-------------------|-------------|----------|
| A2250553251101001 | sample1     | pcb      |

Sample Photo(s)



A2250553251101001



# Test Report

Report No. A225055325110100101

Page 3 of 4

**Test Item: Voltage resistant****1. Test Equipment**

| Equipment Name                               | Model   |
|--|---------|
| AC/DC WITHSTAND<br>VOLTAGE/INSULATION TESTER | TOS9201 |

**2. Environmental Conditions**

Temperature: 23.8 °C; Humidity: 49 %RH

**3. Test Standard: IPC-TM-650 2.5.7D****4. Test Condition**

Test voltage: 1000 VDC; Test duration: 1 min; Voltage rise rate: 100 V/s; Leakage current: 10 mA.

**5. Test Result(s)**

| Test Sample       |   | Test Result                                      |
|-------------------|---|--|
| A2250553251101001 | 1 | No flashover, sparkover and breakdown phenomenon |
|                   | 2 | No flashover, sparkover and breakdown phenomenon |
|                   | 3 | No flashover, sparkover and breakdown phenomenon |

# Test Report

Report No. A225055325110100101

Page 4 of 4

Test Photo:



Test position(s) of sample A2250553251101001

Remark: The testing data and result(s) in this report is(are) just for scientific research, education, internal quality control and product development etc.

**Statement:**

- 1.This report is considered invalid without approved signature, special seal and the seal on the perforation;
- 2.Company Name and Address shown on Report, the sample(s) and sample Information was/were provided by the applicant who should be responsible for the authenticity which CTI hasn't verified;
- 3.The result(s) shown in this report refer(s) only to the sample(s) tested;
- 4.Without written approval of CTI, this report can't be reproduced except in full;
- 5.In case of any discrepancy between the English version and Chinese version of the testing reports(if generated), the Chinese version shall prevail.

\*\*\* End of Report \*\*\*